



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: VAG-002324

Manufacture date: 2014-07

Make: SUBARU

Model: WRX S4

Body: DBA-VAG

Grade: 2.0GT EYESIGHT

Engine: FA20

Drive: 4WD

Transmission: AT

Title information ²:



Registered



Accident / Repair:



No problem



Odometer rollback:



No problem



Manufacturer recall:



No problem



Safety grade ³:



No data



Contamination risk:



Problem found



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-07-08 17:43:35. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	 Not reported				
Malfunction	 Not reported				
Theft	 Not reported				
Fire damage	 Not reported				
Water damage	 Not reported				
Hail damage	 Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2021-08-11	MLIT	61300
2023-08-08	MLIT	84000
2025-06-26	USS Tokyo	102345

USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
 Reported	 Not reported	 Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2014-07			SUBARU	Manufactured
2014-08			MLIT	First registration
2016-08-08	Tochigi		MLIT	Last registration
2021-08-11		61300	MLIT	Inspection
2023-08-08	Tochigi	84000	MLIT	Inspection

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
Not reported			

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
0		0%	0		0%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road



Wet road



VEHICLE SPECIFICATION

1st gear ratio	2nd gear ratio	
3rd gear ratio	4th gear ratio	
5th gear ratio	6th gear ratio	
Additional notes	Airbag position, capacity	
Body rear overhang	Body type	SEDAN

Chassis number embossing position		Classification code	1001
Cylinders	4	Displacement	1990
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	300ps(221kW)/5600rpm	Engine maximum torque	40.8kg· m(400N· m)/2000 ~ 4800rpm
Engine model	FA20	Frame type	
Front shaft weight	940	Front shock absorber type	
Front stabilizer type		Front tires size	225/45R18
Front tread	1530	Fuel consumption	
Fuel tank equipment	60	Grade	2.0GT EYESIGHT
Height	147	Length	459
Main brakes type		Make	SUBARU
Maximum speed		Minimum ground clearance	
Minimum turning radius	5.5	Model	WRX S4
Model code	DBA-VAG	Mufflers number	
Rear shaft weight	600	Rear shock absorber type	
Rear stabilizer type		Rear tires size	225/45R18
Rear tread	1540	Reverse ratio	
Riding capacity	5	Side brakes type	
Specification code	17724	Stopping distance	
Transmission type	AT	Weight	1540
Wheel alignment	4WD	Wheelbase	2650
Width	179		

Date: 2025-06-26, Auction: USS Tokyo, Lot #: 29368

Date:	2025-06-26	Lot #:	29368
Auction name:	USS Tokyo	Region:	Chiba
Make:	SUBARU	Model:	WRX S4
Reg. year:	2014	Mileage (km):	102345
Displacement (cc):	2000	Transmission:	FA
Color:	PEARL	Model code:	VAG
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK


PHOTOS AND AUCTION SHEETS

プライムRコーナー

29368	車種 (車名用以外は記入)		年式	型式	4
	2000		DBA-VAG		
初年度登録年月	車名	グレード	駆動	駆動	
H26/8月	スバル WRX S4	2.0GTアイサイト	4D	4WD	B
車検 R 7 年 8 月 日		シフト	FAT	SR ☒ PS ☒ PB ☒ カワ TV ナビ EFB	
走行 102,345 km		冷房	AAC	セールスポイント	
外色	元色	色番	カラー	・ユーザー買取車！ ・カロツツェリアナビ、TV！ ・プッシュスタート！	
パール			K1X		
燃料	ガソリン	内装色			
輸入区分	ハンドル	車検有効期限	月 日		
リサイクル	12,500円	乗車定員	5人	登録地	宇都宮 301 ち 4372
O注意事項 (修理・不具合修理および状態等)			車台	VAG-002324	
・保、取扱送			シリアル		

O検査員報告

ルーム内スレ汚れ
 シートシミ
 ハンドルハグ
 ホイールキズ
 各キズ凹



長さ	cm	幅	cm	高さ	cm
----	----	---	----	----	----

¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.