



# Vehicle History Report

## VEHICLE DETAILS

**Chassis number <sup>1</sup>:** ZN6-019247

**Manufacture date:** 2012

**Make:** TOYOTA

**Model:** 86

**Body:** DBA-ZN6

**Grade:** GT

**Engine:** FA20

**Drive:** 2WD

**Transmission:** F6

**Title information <sup>2</sup>:**



**Deregistered to Export**



**Accident / Repair:**



**No problem**



**Odometer rollback:**



**No problem**



**Manufacturer recall:**



**No problem**



**Safety grade <sup>3</sup>:**



**★★★★**



**Contamination risk:**



**No problem**



This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-11-26 23:46:16. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

## ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2021-09-17	MLIT	78300
2023-09-11	MLIT	100100
2024-05-10	USS Nagoya	106440
2025-10-24	USS Osaka	109100

## USE HISTORY

<b>Use in the contaminated regions <sup>4</sup></b>	<b>Radioactive contamination test fail <sup>5</sup></b>	<b>Commercial use</b>
Not reported	Not reported	Not reported

## DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2012			TOYOTA	Manufactured
2012-09			MLIT	First registration
2021-09-17		78300	MLIT	Inspection
2023-09-11	Nagoya	100100	MLIT	Inspection

2024-05-10	Aichi	106440	USS Nagoya	Auctioned
2025-08-28	Nagoya		MLIT	Last registration
2025-10-24	Osaka	109100	USS Osaka	Auctioned

## MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
---------------	-------------	---------------	---------

 Not reported

## VEHICLE ASSESSMENT <sup>6</sup>

### Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
10.27	★★★★★	86%	10.16	★★★★★	85%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

### Braking performance tests <sup>7</sup>

Dry road		39.6 m
Wet road		41.0 m

## VEHICLE SPECIFICATION

<b>1st gear ratio</b>	3.626( SYNCHRONIZER)	<b>2nd gear ratio</b>	2.188( SYNCHRONIZER)
<b>3rd gear ratio</b>	1.541( SYNCHRONIZER)	<b>4th gear ratio</b>	1.213( SYNCHRONIZER)
<b>5th gear ratio</b>	1.000( SYNCHRONIZER)	<b>6th gear ratio</b>	0.767( SYNCHRONIZER)

<b>Additional notes</b>	-	<b>Airbag position, capacity</b>	
<b>Body rear overhang</b>	755 ( REAR SPOILER HAVE ) 750 ( REAR SPOILER LESS )	<b>Body type</b>	COUPE
<b>Chassis number embossing position</b>	CROSSMEMBER FRONT RIGHT SIDE FRONT SURFACE	<b>Classification code</b>	1008
<b>Cylinders</b>		<b>Displacement</b>	1990
<b>Electric engine type</b>	-	<b>Electric engine maximum output</b>	-
<b>Electric engine maximum torque</b>	-	<b>Electric engine power</b>	-
<b>Engine maximum power</b>	200ps(147kW)/7000rpm	<b>Engine maximum torque</b>	20.9kg· m(205N· m)/6400 ~ 6600rpm
<b>Engine model</b>	FA20	<b>Frame type</b>	FRAME LESS
<b>Front shaft weight</b>	690	<b>Front shock absorber type</b>	
<b>Front stabilizer type</b>	TORSION· BAR TYPE	<b>Front tires size</b>	215/45R17 87W
<b>Front tread</b>	1520	<b>Fuel consumption</b>	-
<b>Fuel tank equipment</b>	50	<b>Grade</b>	GT
<b>Height</b>	1.300	<b>Length</b>	4.240
<b>Main brakes type</b>	HYDRAULIC TYPE FRONT DISK BACK DISK	<b>Make</b>	TOYOTA
<b>Maximum speed</b>		<b>Minimum ground clearance</b>	0.130
<b>Minimum turning radius</b>	5.4	<b>Model</b>	86
<b>Model code</b>	DBA-ZN6	<b>Mufflers number</b>	
<b>Rear shaft weight</b>	540	<b>Rear shock absorber type</b>	
<b>Rear stabilizer type</b>	TORSION· BAR TYPE	<b>Rear tires size</b>	215/45R17 87W
<b>Rear tread</b>	1540	<b>Reverse ratio</b>	3.437( SYNCHRONIZER)
<b>Riding capacity</b>	4	<b>Side brakes type</b>	
<b>Specification code</b>	17116	<b>Stopping distance</b>	☆7.72(100)
<b>Transmission type</b>	F6	<b>Weight</b>	1230

Wheel alignment	2WD	Wheelbase	2570
Width	1.775		

## AUCTION DATA

### Date: 2024-05-10, Auction: USS Nagoya, Lot #: 50585

Date:	2024-05-10	Lot #:	50585
Auction name:	<a href="#">USS Nagoya</a>	Region:	Aichi
Make:	TOYOTA	Model:	86
Reg. year:	2012	Mileage (km):	106440
Displacement (cc):	2000	Transmission:	F6
Color:	SILVER	Model code:	ZN6
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

### Date: 2025-10-24, Auction: USS Osaka, Lot #: 20204

Date:	2025-10-24	Lot #:	20204
Auction name:	<a href="#">USS Osaka</a>	Region:	Osaka
Make:	TOYOTA	Model:	86
Reg. year:	2012	Mileage (km):	109100
Displacement (cc):	2000	Transmission:	F6
Color:	SILVER	Model code:	ZN6
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

## PHOTOS AND AUCTION SHEETS

# プライム②コーナー


50585	車種 (車名以外は記入)	排気量	型式	内装 4 B
	初年度登録年月	車名	グレード	
	24/9月	86	20 GT	

車検	7年 9月	ソフト	F6	SR	AW	CB	CD
走行	106440 Km	冷房	AAC	カワ	TV	ナビ	E20
外色	シルバー	カラー	06S	セールスポイント ★ユーザー買取車★ ★ワンオーナー★ ★オプションスタート・スタートキー★ ★マフリン			
内装	ベージュ	内装色	ベージュ	*車種と一致しない場合は記入			
輸入業者	ディーラー	並行	左・右	名義変更期間			

リサイクル 廃棄金	10,180 円	乗車定員	人	登録地	愛知	登録番号	300 47 6782
○注意事項 (修理・不具合等のあるよび故障等)				車台記	ZN6-019247		
オネフシス: 2000cc				シリアル記			

## ○検査員報告 (USS使用済)

2000cc  
 2000cc 2000cc  
 2000cc 2000cc  
 2000cc 2000cc



両台内寸的	X	X	(cm)
長さ	cm	高さ	cm

※ (車検屋上の寸法)

# プライムタイムコーナー


20204	車種(車名以外は記入)	排気量	型式	7人座 4
		2000	DBA-ZN6	
	初年度登録年月 H24/9月	車名 トヨタ	グレード GT	内装 B
	86	CP	ZND	

車検	年月日	シフト	F6	燃費	SR カワ	PS ナビ	PA エア
走行	109,100 km	冷機	AAC	セールスポイント			
外色	色番 シルバー	カラー名	D6S	★カーブレイナビ			
燃料	ガソリン	内装色	ブラック系	★バックカメラ			
輸入車	輸入国	ハンドル		★ETC ★ドライブレコーダー			
				★スマートキー・PUSHスタート			
				★キセノンライト			

リサイクル 標章	10,180円	乗車定員	4人	登録地	
○注意事項(事故・不具合箇所および故障等)				車台	ZN6-019247
・H27・29・R1・R3年車検時 記録簿あり!				シリアル	
・自社名変更ワンオーナー車!					
・保証書・取説・記録簿・スペアキー即日発送!					

## ○検査員報告

- ルーム内一部汚れ
- ホイールキズ
- 小キズ小凹



【脚台内寸】約	X	X	(cm)
長さ	424 cm	幅	177 cm
		高さ	130 cm

**<sup>1</sup> Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

**<sup>2</sup> Title information:**

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

**<sup>3</sup> Determining the overall collision safety performance evaluation** – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

**<sup>4</sup> Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

**<sup>5</sup> Radioactive contamination test** – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

**<sup>6</sup> Japan New Car Assessment Program** – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

**<sup>7</sup> Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.